

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

Joseph Lloyd Manor House
Lloyd Harbor Road
Lloyd Harbor
Suffolk County
New York

HABS No. NY-5670

Documentation: 8 sheets (1979, including site plan, plans, elevations, section)
7 exterior photos (1979)
17 interior photos (1979)
1 set of field records (including 7 field notebooks, 150
photograph negatives, 4 contact sheets)

Walter Smalling, photographer October 1979

- NY-5670-1 General view of house, from southeast
- NY-5670-2 South (front) elevation
- NY-5670-3 General view of east elevation
- NY-5670-4 South and west elevations
- NY-5670-5 General view of north (rear) elevation
- NY-5670-6 Detail of main entrance, south elevation
- NY-5670-7 Original window on right being re-installed, on northeast corner of east side of house
- NY-5670-8 General view of first floor stairhall, looking north
- NY-5670-9 General view of stairhall, looking south
- NY-5670-10 Detail of front entrance door with sidelights
- NY-5670-11 Detail of newel post and balusters, first floor stairhall, south side
- NY-5670-12 Detail of rail and balusters, south side stairway
- NY-5670-13 Paneled woodwork on north wall of first floor southeast corner room
- NY-5670-14 First floor southwest room with fireplace and paneled woodwork on north wall

(continued)

Joseph Lloyd Manor House
HABS No. NY-5670 (page 2)
Index to Photographs

- NY-5670-15 Detail of door and pilasters on north wall of southwest room on first floor
- NY-5670-16 Woodwork details of east wall in first floor northeast corner room
- NY-5670-17 Fireplace on south wall of first floor northeast corner room
- NY-5670-18 Stairhall with wainscoting and door frame details on west wall of second floor south end
- NY-5670-19 View to south of second floor stairhall
- NY-5670-20 Second floor stairhall on south side
- NY-5670-21 Fireplace on north wall of second floor southeast room
- NY-5670-22 Second floor southwest room with fireplace and arched openings on north wall
- NY-5670-23 Detail of window on south wall of second floor southwest corner room
- NY-5670-24 Detail of shutters closing window on south wall of second floor southwest corner room